

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO; IL 60604-3590

MAY 1 2 2017

REPLY TO THE ATTENTION OF:

Ms. Carol Westling Federated Co-op 925 Highway 47 South Isle, Minnesota 56342

Re: Compliance Evaluation Inspection

Dear Ms. Westling:

On October 28, 2016, a representative of the U.S. Environmental Protection Agency inspected the Federated Co-op located in Isle, Minnesota. The purpose of the inspection was to evaluate the facility's compliance with certain requirements of the Resource Conservation and Recovery Act (RCRA), specifically the technical standards and corrective action requirements for owners and operators of underground storage tanks set forth at 40 Code of Federal Regulations Part 280. Enclosed please find a copy of our inspection report dated October 28, 2016.

The inspector noted a crack in your premium spill bucket; however, upon further review this did not appear to be a violation. It is recommended that you get this fixed as soon as possible, before it becomes an issue.

Based upon the information available to the EPA, the inspection did not detect any violations of the specific RCRA requirements under evaluation. This determination does not limit the applicability of the requirements evaluated, other RCRA regulations, or regulations under other environmental statutes. The EPA will continue to evaluate your facility in the future.

If you have any questions or concerns regarding this matter, please contact Mark Restaino, of my staff, at 312-886-0394.

Sincerely,

Sherry A. Karnke, Chief

Underground Storage Tanks Section

henry a. Kumh

Enclosure

cc: Ryan Rupp, Department of Natural Resources, Mille Lacs Band of Ojibwe Indians Andrew Boyd, Department of Natural Resources, Mille Lacs Band of Ojibwe Indians

UST Inspection Checklist								
		PAR	T L OWNER/OPER	RATOR INFORMA	TION			
1. Facility Name: Federated CO-OP				6. Date of Visit: 10/28/16 7. Marketer: x Non-Marketer:				
2. Owner: Federated CO-OP				8. Site Arrival/Departure (Time): 12:05pm / 1:15pm				
3. Operator:	-		AND THE PROPERTY OF THE PROPER	9. Facility Address: 925 South Hwy 47				
5. Contact Person: Carol Westling				Isle. MN 56342				
6. UST Site Phone #: 320-676-3863 10: Team Members: Ryan Rupp/Andrew Boyd/Carol W							d/Carol Westling	
PART II. UST SITE INFORMATION								
1. Tank #:		2	3	4	5	6	7	
2. Tank Type:	STT-P3	STI-P3	STI-P3	STI-P3	STI-P3			
3. Piping Type:	Wrapped Steel	Wrapped Steel	Wrapped Steel	Wrapped Steel	Wrapped Steel	distribution designation and a state of the		
4. Size of Tank:	12,000	10,000	6000	000,00	4000	satisfaceout de la companya de la co		
5. Tank Contents:	Reg. UL	Mid UL	Prem. UL	Diesel 2	Diesel	### ##################################	LA PLANCE DE LA CONTRACTION DE	
6. Install Date:	4/9/1990	4/9/1990	4/9/1990	4/9/1990 .	4/9/1990	***************************************	Charles and the Charles and Ch	
7. TTT Date:			***************************************	Seriority and the serior of th	***************************************	amenament comments of security and a security of the security		
8. LTT Date:	***************************************		-	AND MAIN COMMANDER WHEN THE WASHINGTON TO SHARE THE WASHINGTON THE	Solution Anna American and American American	wira-e-mar-vine-vine-e-vine-vine-vine-	· · · · · · · · · · · · · · · · · · ·	
9: LD (Tank):	ATG	ATG	ATG	ATG	ATG			
10: LD (Pipe):	ELLD	ELLD	ELLD	ELLD	ELLD			
11. Closure Date:								
	PermTemp	PermTemp	Репя Тепф	РегтТетр	РегтТетр	РегипТенир	PermTemp	
12. Spill:	Yes_x_No	YesNo	Yes x No _	Yes_x No	Yes_x No _	Yes_ No _	Yes_No_	
13. Overfill:						YesNo	Yes No	
Type:	Alarm	Alarm	Alarm	Alarm	Alarm			
14. CP (Tank): Date:	Yes x No 10/26/2016	Yes No Due 10/26/17	Yes No	Yes_No_	Yes No	YesNo	Yes No	
Type:	Impressed	Current			400000000000000000000000000000000000000			
15. CP (Piping):	YesNo	Yes_No_	Yes No	Yes_No_	Yes _ No _	YesNo	Yes No	
Date:	10/26/2016 Impressed	Due 10/26/17 Current		and the state of t			**************************************	
Type: Impressed Current 16. CP Monitoring: [For all cathodic protection systems (Galvanic Anodes and Impressed Current Systems)]								
6 Mo./3 Yrs:	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	
Six Months:	Yes No	Yes No	Yes No	Yes _ No_		Yes No	Yes _ No _	
Records:	Yes No	Yes No	Yes No		Yes No	Yes No	Yes No	
Note: Records on file of last two monitoring results. [280.31(d)(2)) 17. CP Monitoring: [For Impressed Current Systems Only]								
60 Day Insp.:	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	
Note: System is Records:	inspected ever 60 da	ys, involvers reading Yes No	and recording system	ns voltage and ampen	ige. [280.31(c)]		Yes No	
E		oltage and amperage r			110 110	1-5 140	125 110	

UST Inspection Checklist							
PART IIL RECOMMENDATION(S) & NARRATIVE COMMENTS							
Further action is recommend/necessary: YesNo	5. Notice of Violation (NOV): Yes No Date:						
Notes:	Notes:						
	[If Yes, A Full Narrative Report is required along with this checklist]						
2. Facility to provide info. on compliance: Yes No	6. Field Citation (FC): Yes No Date:						
Notes:	Notes: [If Yes, A Full Narrative Report is required along with this checklist]						
II DE LES CONTRACTOR DE LES CO	· — · -						
3. Follow-up inspection recommended: Yes No	7. Administrative Order (AO): Yes No Date:						
Notes: [If Yes, state reason(s) why.]	Notes: [If Yes, A Full Narrative Report is required along with this checklist]						
4. Information Request Letter (IRL): Yes No Date:	8. Refer to State: Yes No Date:						
~							
Notes: [If Yes, A Full Narrative Report is required along with this checklist]	Notes: [If Yes, A Full Narrative Report mey be required along with this checklist]						
9. Financial Responsibility (FR): Yes x No Expiration Date: Minnesota Petrofund							
10. Inspector's Remarks: Handed out the Updated 2015 Must for USTs and Implementation Time Frames for 2015 UST Brochure							
Discussed the new 2015 regulations. Under-dispenser containment for new dispenser systems, operator training, spill prevention equipment testing, overfill prevention equipment inspections, containment sump testing, release detection equipment testing &							
walkthrough inspections. Spill buckets, sumps and under dispenser containment are all dry except tank 4 & 5 spill buckets have small amount of product –							
recommended to clean out. Premium spill bucket is cracked near the top – recommended to repair/replace.							
CP passed 10/26/2016. Federated does annual CP due again 10/26/2017.							
Checked Rectifier 16V / 6.4 Amps 47390 hours. See attach Monthly Rectifier Readings.							
Annual Mechanical/ Electronic Leak Detection performed 10/27/16.	. See attached.						
11. Additional Remarks/Comments:							
Tank Test T1 T2 T3 T4 T5 Line Test were o	observed also. Had 12 consecutive months of multiple passes at						
10/3/2016 Pass P P P P .2 GPH and annu	ual .1GPH. See Attached photo of an example of printout for						
9/1/2016 P P P P P each month. All	l lines passed each month. November 2015 thru October 2016.						
8/1/2016 P P P P P							
7/1/2016 P P P P P							
6/1/2016 P P P P P S/11/17-	After further Review the						
5/2/2016 P P P P P	Spill Backet Appears TO						
4/1/2016 P P P P P	Function As required. Recommend						
3/1/2016 P P P P P	repair or replading before						
2/1/2016 P P P P P	it is an issue MUR 5/11/17						
12/31/2015 P P P P P	. 1						
12/1/2015 P P P P P							
11/2/2015 P P P P P							
Payn Hugg 10/0	28/16 Date						

No Further Actions Moule Rotters 5/11/17